SMOKE AND DYED WA	Page 1 of 3			
Sewershed: Low Level Subsewershed: 42	Company: REI/DRAYCO	Date: 08/12/2008 Supervisor: E.R. Crew: 04 Notifications Made:X Residents, Fire, 311		
Test Type: Smoke	Ground Condition: Dry: X Damp: _ Wet: _			
Manhole ID: S19W027MH	Test ID: 1029-538			
	umbers, blower placement location, sandba	~		
addresses	and locations, defect locations and photog	raph numbers)		
	1 ,			
2312	026			
	16" (459)			
	July 1			
		005		
004	25	BLOWER #1 S19W027MH		
		319W027WIT		
//88/				
538	3_OB01-01			
1 1/2/	XX 3 1818	27		
(10)/1/	The second second	XX / XX		
1/8/13		35 03		
V \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	\$ / / /	132		
	009	131		
	// //	11 131 -		
	1/38/1/20			
019				
	JAMES ST.			
	2 / / / / / / / / / / / / / / / / / / /	022		
	49/	00000		
		028DE		
1/ N/N/ / / /		X / // //		

CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM							Page 2 of 3		
S	Sewershed: Low Level Subsewershed: 42	Company: REI/DRAYCO			0	Date: 08/12/2008			
	Test Type: Smoke	Ground Condition: Dry: X Damp:_ Wet:_				Supervisor: E.R. Crew: 04			
Mar	nhole ID: S19W027MH	Test ID: 1029-538			•	Notifications Made:X_ Residents, Fire, 311			
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)									
Defect No.		Source Type	Location		Draina Area		Photo Number		
1	2320 JAMES ST.	03	09	02	3	3	1029-538_OB01-01.jpg		
-									
-									
-		+							
-									
			1						
-									
-									
		+							
		OF	I SSERVAT	ION COL)FS				
OBSERVATION CODES Source Type Location Sector Severity									
01 Ma	ain Sewer 10 MH Frame	01 Paved C		Non-Pav	ed 0		01 No Smoke		
02 Se	ervice Line 11 Storm Drain	02 Asphalt	11	Field/Wo		2 Private	02 Trace		
03 Cleanout 12 Catch Basin				Alley			03 Moderate		
04 Downspout 13 Storm MH				Golf Cou	rse		04 Major		
	ea Drain 14 Storm Ditch	05 Sidewall	(14	Other	—⊩				
	vy. Drain 15 Excavation air. Drain 16 Water Line	06 Curb 07 Yard - F	ront		—⊩				
	ound. Drail 17 Tele. Pole	08 Yard - B							
	09 Bldg. Interio 18 Other		ide						
	J 12 1 2 1 2 1 1 1 2 1 1 1 2 1 1 1 2 1 1 1 1 2 1 1 2 1	09 Yard - S	-	1			II		

PAGE 3 OF 3

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 538 Date: 08/12/2008 Basin: LL - 42 Manhole ID: S19W_027MH Defect No: OB01 Supervisor: E.R. Crew: 04 Dye Test Recommended: N

Location: 2320 JAMES ST.

Source Type: 03 Cleanout Location: 09 Yard - Side

Sector: 02 Private Severity: 03 Moderate Drainage Area: 3

Comments: SMOKE COMING FROM AT GRADE CLEANOUT IN SIDE YARD.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01 Filename: 1029-538_OB01-01.jpg